



Volvo XC90 (MKL): 2BAD319

Vinnumber:	YV1LFBMVDN1786609	Versionname:	XC90 Inscription 2.0T8 Hybrid 303pk/cv 5p 7pl AWD Geartronic
First Registrationdate:	6/09/2021	Fiscalpower:	
Expertise Mileage:	119536	Power Kw:	223
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	dans 23295 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

275/45/20/110 V				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				275/45 R 20 110 V
Tyre size FR				275/45 R 20 110 V
Tyre size RL				275/45 R 20 110 V
Tyre size RR				275/45 R 20 110 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		

Bumper F, Scratch(es), Spot repair



Bonnet, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Wing trim RL, Scratch(es), Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Check



Tailgate / Boot, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Wing trim FR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Acceptable

