



Volvo XC90 (MKL): 2CAE305

Vinnumber:	YV1LFH5VDN1864524	Versionname:	XC90 Inscription 2.0T8 PHEV 455pk/cv 5p 7pl AWD Geartronic
First Registrationdate:	9/05/2022	Fiscalpower:	
Expertise Mileage:	132745	Power Kw:	228
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	25475.0		
Maintenance	over 333 dagen		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

275/45/20/110 V				
Winter tyres:	Fr.L.	Firestone: 2 mm	Fr.R.	Firestone: 2 mm
	Re.L.	Firestone: 2 mm	Re.R.	Firestone: 2 mm
Tyre profile depth FL	2.0			
Tyre profile depth FR	2.0			
Tyre profile depth RL	2.0			
Tyre profile depth RR	2.0			
Tyre size FL	275/45 R 20 110 V			
Tyre size FR	275/45 R 20 110 V			
Tyre size RL	275/45 R 20 110 V			
Tyre size RR	275/45 R 20 110 V			
Tyre type FL	Winter			
Tyre type FR	Winter			
Tyre type RL	Winter			
Tyre type RR	Winter			
Tyre make FL	258			
Tyre make FR	258			
Tyre make RL	258			
Tyre make RR	258			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		

Seat cover FL, Worn, Acceptable



Backrest cover FR, Tear, Replace



Door panel RR, Scratch(es), Smart repair



Engine insulation, Damaged, Replace



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)





Tailgate / Boot, Scratch(es), Spot repair



Charging cable (normal), Missing, Replace



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Tyre RR, Tear, Replace



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Bodywork, Dirty, Check

