



VOLVO V40: 1VBE725

Vinnumber:	YV1MV70V1K2560122	Versionname:	D2 Black Edition
First Registrationdate:	12/09/2018	Fiscalpower:	
Expertise Mileage:	117689	Power Kw:	88
Bodytype:		Body colour:	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2210
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

205/55/16/92 V				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 92 V
Tyre size FR				205/55 R 16 92 V
Tyre size RL				205/55 R 16 92 V
Tyre size RR				205/55 R 16 92 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	1798,29
Steering wheel, Worn, Acceptable:	0,00



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)

289,07



Alloy rim RL, Scratch(es), Repair and paint (complete)

129,66



Outside rear-view mirror L, complete, Scratch(es), Acceptable

0,00



Boot cover, Broken, Replace

66,00



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)

416,51



Wing RR, Dent(s), Acceptable

0,00



Door FR, Dent(s) and scratch(es), Repair and paint (complete)

492,50



Alloy rim RR polished, Deformed / Strained, Replace

284,55



Door RR, Dent(s) and scratch(es), Acceptable

0,00



Tyres, Not original part, Forfeit

120,00

