

Inspection Protocol

VOLVO V90 D4

Vehicle information

License plate	WSF756	Inspected by	T.H.
Year model	2019	Date of inspection	2025-10-22
Manuf. year/month	2018-06	City	Björkvik
First day in traffic	2018-06	Keys	2
Colour	Svart	Service book	Ja
Mileage	132 450 km	Latest service	2025-09-15
Fuel	Diesel	Mileage at the latest service	130 000 km
Transmission	Geartronic	Summer tires	18" alu-fälg 3/3/5/5
Engine effect	140 kW	Winter tires	alu-fälg dubbat 5/5/5/5

Damages

Location	Damage	Comments	Costs excluding VAT
Bumper, Rear	Repa/Repor		290 €
Boot lid, Boot lid	Repa/Repor		150 €
Lamps, Bakljus	Byte		220 €
Bumper, Front	Repa/Repor		260 €
Glass, Windshield	Stenskott/Spricka		-
Recond, Dirty trim	Klädsel tvätt		150 €

Total excl. VAT	1 070 €
------------------------	----------------

Images

[See all images in large format](#)















SERVICE OCH UNDERHÅLL

Service Nr. 6	Service Nr. 7	Service Nr. 8
Utförd km 13000	Utförd km	Utförd km
Datum 15/09/25	Datum	Datum
Arbetsorder nr. 3022813	Arbetsorder nr.	Arbetsorder nr.
Typ av service	Typ av service	Typ av service
Bilbolaget Bilbolaget Personbilar Sundsvall AB Kundmottagning	Basservice	Basservice
Underhållsservice	Underhållsservice	Underhållsservice
Bilbolaget Bilbolaget Personbilar Sundsvall AB Kundmottagning	Anpassad basservice	Anpassad basservice
Intervalltillägg/Övrigt	Intervalltillägg/Övrigt	Intervalltillägg/Övrigt

8















