


Vehicle details

VIN	YV1PWH1VD N1179746	Brand	VOLVO	Maintenance date	-
Licence Plate	P4-67-FS	Model	V90 Recharge T6 AWD R-Design 5d	Maintenance mileage	-
Registration date	25/02/2022	Year	2022	Exterior Color	Blue Metallic
Odometer	171 670 km	Engine size	1969	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	19/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Sliding roof	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
4x4	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Load cover	✓
Vehicle charger	✓
Wireless charger	✗

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 245/45/18 Summer 4.0 mm



Continental 245/45/18 Summer 4.0 mm



Continental 245/45/18 Summer 4.5 mm

Continental 245/45/18 Summer 4.5 mm

Exterior

2



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

3



Part	Wing
Position	Back right
Damages	Dented
Severity	-
Repair mode	Repair

4



Part	Alloy wheel 18"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

5



Part	Alloy wheel 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

6



Part	Bonnet
Position	-
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

7



Part	Spoiler
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

8



Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	Repair

9



Part	Roof
Position	-
Damages	Rusty
Severity	-
Repair mode	Lumpsum repair

10



Part	Alloy wheel 18"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

Others

1



Part	Wireless charger
Position	-
Damages	Missing
Severity	-
Repair mode	For info