

Inspection Protocol



VOLVO V90 RECHARGE T6 AWD INSCRIPTION EXPRESSION

Vehicle information

License plate	FFB06P	Inspected by	T.H.
Year model	2022	Date of inspection	2025-04-14
Manuf. year/month	2022-01	City	Björkvik
First day in traffic	2022-01	Keys	2
Colour	Svart	Service book	Ja
Mileage	123 550 km	Latest service	2024-09-09
Fuel	Elhybrid	Mileage at the latest service	101 710 km
Transmission	Geartronic	Summer tires	18" alu-fälg 1/1/2/2
Engine effect	257 kW	Winter tires	alu-fälg dubbat 5/5/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Rims & Tires, Summer	4 tires below 3 mm		430 €
Door, Front left	Dörruppslag		-
Wing, Rear left	Scratches 30-100 mm		80 €
Wing, Rear right	Scratches 30-100 mm		80 €
Glass, Windshield	Chip		20 €
Rims & Tires, Summer	Rim damage 1 wheel		110 €
Tak, Tak	Chip		60 €
Total excl. VAT			780 €

Service occasions

3000-MIL, 6500-MIL, 10000-MIL

Images

[See all images in large format](#)













Service Nr. 1

Utförd km: 30218

Datum: 23-01-20

Arbetsorder nr: 3953580

Typ av service: **Tago Rejmes i Norrköping Bil AB**
Jesper Adolfsson
Personlig servicetekniker

Underhållsservice

Ärpassad basservice

Intervalltagg/Övrigt

Service Nr. 2

Utförd km: 66062

Datum: 23-12-01

Arbetsorder nr: 4092199

Typ av service: **Tago Rejmes i Norrköping Bil AB**
Jesper Adolfsson
Personlig servicetekniker

Underhållsservice

Ärpassad basservice

Intervalltagg/Övrigt

Service Nr. 3

Utförd km: 101718

Datum: 24-09-09

Arbetsorder nr: 4219317

Typ av service: **Tago Rejmes i Norrköping Bil AB**
Hampus Eriksson
Personlig servicetekniker

Underhållsservice

Ärpassad basservice

Intervalltagg/Övrigt

Service Nr. 4

Utförd km:

Datum:

Arbetsorder nr:

Typ av service:

Underhållsservice

Ärpassad basservice

Intervalltagg/Övrigt











Dörr Vänster fram Dörruppslag



Skärm Vänster bak Repor 3-10 cm 1 100 kr



Skärm Höger bak Repor 3-10 cm 1 100 kr



Glas Vindruta Stenskott 300 kr



Fälgar & Däck Sommar Fälgskada 1 hjul 1 500 kr



Tak Tak Stenskott 800 kr