


**Vehicle details**

VIN	YV1PWH1VD N1181530	Brand	VOLVO	Maintenance date	-
Licence Plate	P9-74-JK	Model	V90 Recharge T6 AWD R-Design 5d	Maintenance mileage	-
Registration date	29/03/2022	Year	2022	Exterior Color	Brown Metallic
Odometer	124 870 km	Engine size	1969	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

**Inspection Details**

Inspection date	17/10/2025	Inspection loc.	Dekra Ayvens		
					
					
					

**Generic equipment**

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


**Removable element**

Load cover	✓
Vehicle charger	✓
Wireless charger	✗

**Technical Document**

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

**Tyres**

Michelin 245/45/18 Summer 4.5 mm		Michelin 245/45/18 Summer 4.5 mm	
Michelin 245/45/18 Summer 5.0 mm		Michelin 245/45/18 Summer 4.5 mm	

## Exterior

2		<table border="1"> <tr><td>Part</td><td>Alloy wheel 18"</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 18"	Position	Front left	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair	3		<table border="1"> <tr><td>Part</td><td>Alloy wheel 18"</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 18"	Position	Back left	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair
Part	Alloy wheel 18"																								
Position	Front left																								
Damages	Scratched																								
Severity	-																								
Repair mode	Lumpsum repair																								
Part	Alloy wheel 18"																								
Position	Back left																								
Damages	Scratched																								
Severity	-																								
Repair mode	Lumpsum repair																								
4		<table border="1"> <tr><td>Part</td><td>Alloy wheel 18"</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 18"	Position	Back right	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair	5		<table border="1"> <tr><td>Part</td><td>Alloy wheel 18"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 18"	Position	Front right	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair
Part	Alloy wheel 18"																								
Position	Back right																								
Damages	Scratched																								
Severity	-																								
Repair mode	Lumpsum repair																								
Part	Alloy wheel 18"																								
Position	Front right																								
Damages	Scratched																								
Severity	-																								
Repair mode	Lumpsum repair																								
6		<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) &gt; 20</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Front	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Repair	7		<table border="1"> <tr><td>Part</td><td>Windscreen</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stone impact</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Windscreen	Position	-	Damages	Stone impact	Severity	-	Repair mode	For info
Part	Bumper																								
Position	Front																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Repair																								
Part	Windscreen																								
Position	-																								
Damages	Stone impact																								
Severity	-																								
Repair mode	For info																								

## Others

1		<table border="1"> <tr><td>Part</td><td>Wireless charger</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Wireless charger	Position	-	Damages	Missing	Severity	-	Repair mode	For info
Part	Wireless charger											
Position	-											
Damages	Missing											
Severity	-											
Repair mode	For info											