

Vehicle details

VIN	YV1PWK9VD M1161471	Brand	VOLVO	Maintenance date	-
Licence Plate	K4-81-JX	Model	V90 B4 Automaat Inscription 5d	Maintenance mileage	-
Registration date	05/01/2021	Year	2021	Exterior Color	Brown Metallic
Odometer	161 211 km	Engine size	1969	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	15/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Sliding roof	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Tow	✓
Metallic paint	✓
Electric windows	✓
4x4	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 235/35/20 Summer 6.5 mm



Michelin 235/35/20 Summer 7.0 mm



Michelin 235/35/20 Summer 5.0 mm

Michelin 235/35/20 Summer 5.0 mm

Exterior

1



Part	Panoramic Roof
Position	Back
Damages	Broken
Severity	-
Repair mode	Replace

4



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

5



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

6



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

7



Part	Alloy wheel 20"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

8



Part	Wing
Position	Front left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

9



Part	Door Frame seal
Position	Back left
Damages	Not conform
Severity	-
Repair mode	Replace

10



Part	Alloy wheel 20"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

11




Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

12



Part	Tailgate / Boot door
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

13



Part	Alloy wheel 20"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

14



Part	Roof post A/B/C
Position	Right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

15



● ●

Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

16



● ●

Part	Wing
Position	Front right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

17



● ● ●

Part	Alloy wheel 20"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair


Interior damage

2



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

3



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning