


DEKRA Automotive Solutions

Vehicle details

VIN	YV1PZA8U4 K1078176	Brand	VOLVO	Maintenance date	22/11/2024
Licence Plate	WMP324	Model	V90Kombi-2016	Maintenance mileage	150 003 km
Registration date	14/12/2018	Year	2018	Exterior Color	Other
Odometer	162 236 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	16/09/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Refill emergency kit	✓
Load cover	✓
Towing hook	✓

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Spare key	✓
Key	✓
Remote key	✓

DEKRA Automotive Solutions

Tyres


Pirelli 235/55/18 Y Summer 3.0 mm		Pirelli 235/55/18 Y Summer 3.0 mm	
Pirelli 235/55/18 Y Summer 2.0 mm		Pirelli 235/55/18 Y Summer 2.0 mm	

Winter kit

Goodyear 235/55/18 T Winter 8.0 mm		Goodyear 235/55/18 T Winter 8.0 mm	
Goodyear 235/55/18 T Winter 8.0 mm		Goodyear 235/55/18 T Winter 8.0 mm	

Damages

1		Part	Aftermarket wheel	2		Part	Aftermarket wheel
		Position	-			Position	-
3		Damages	Scratched	4		Damages	Scratched
		Severity	-			Severity	-
5		Repair mode	Lumpsum replacement	6		Repair mode	Lumpsum replacement
		Part	Bumper			Part	Bumper
7		Position	Front	8		Position	Front
		Damages	Scratched			Damages	Scratched
9		Severity	-	10		Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Lumsum Paintworks
11		Part	Exterior door mirror shell	12		Part	Door
		Position	Front left			Position	Front left
13		Damages	Scratched	14		Damages	Scratched
		Severity	-			Severity	-
15		Repair mode	For info	16		Repair mode	Lumsum Paintworks
		Part	Bumper			Part	Bumper
17		Position	Front	18		Position	Front
		Damages	Scratched			Damages	Scratched
19		Severity	-	20		Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Lumsum Paintworks
21		Part	Exterior door mirror shell	22		Part	Door
		Position	Front left			Position	Front left
23		Damages	Scratched	24		Damages	Scratched
		Severity	-			Severity	-
25		Repair mode	For info	26		Repair mode	Lumsum Paintworks
		Part	Bumper			Part	Bumper
27		Position	Front	28		Position	Front
		Damages	Scratched			Damages	Scratched
29		Severity	-	30		Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Lumsum Paintworks
31		Part	Exterior door mirror shell	32		Part	Door
		Position	Front left			Position	Front left
33		Damages	Scratched	34		Damages	Scratched
		Severity	-			Severity	-
35		Repair mode	For info	36		Repair mode	Lumsum Paintworks
		Part	Bumper			Part	Bumper
37		Position	Front	38		Position	Front
		Damages	Scratched			Damages	Scratched
39		Severity	-	40		Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Lumsum Paintworks
41		Part	Exterior door mirror shell	42		Part	Door
		Position	Front left			Position	Front left
43		Damages	Scratched	44		Damages	Scratched
		Severity	-			Severity	-
45		Repair mode	For info	46		Repair mode	Lumsum Paintworks
		Part	Bumper			Part	Bumper
47		Position	Front	48		Position	Front
		Damages	Scratched			Damages	Scratched
49		Severity	-	50		Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Lumsum Paintworks
51		Part	Exterior door mirror shell	52		Part	Door
		Position	Front left			Position	Front left
53		Damages	Scratched	54		Damages	Scratched
		Severity	-			Severity	-
55		Repair mode	For info	56		Repair mode	Lumsum Paintworks
		Part	Bumper			Part	Bumper
57		Position	Front	58		Position	Front
		Damages	Scratched			Damages	Scratched
59		Severity	-	60		Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Lumsum Paintworks
61		Part	Exterior door mirror shell	62		Part	Door
		Position	Front left			Position	Front left
63		Damages	Scratched	64		Damages	Scratched
		Severity	-			Severity	-
65		Repair mode	For info	66		Repair mode	Lumsum Paintworks
		Part	Bumper			Part	Bumper
67		Position	Front	68		Position	Front
		Damages	Scratched			Damages	Scratched
69		Severity	-	70		Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Lumsum Paintworks
71		Part	Exterior door mirror shell	72		Part	Door
		Position	Front left			Position	Front left
73		Damages	Scratched	74		Damages	Scratched
		Severity	-			Severity	-
75		Repair mode	For info	76		Repair mode	Lumsum Paintworks
		Part	Bumper			Part	Bumper
77		Position	Front	78		Position	Front
		Damages	Scratched			Damages	Scratched
79		Severity	-	80		Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Lumsum Paintworks
81		Part	Exterior door mirror shell	82		Part	Door
		Position	Front left			Position	Front left
83		Damages	Scratched	84		Damages	Scratched
		Severity	-			Severity	-
85		Repair mode	For info	86		Repair mode	Lumsum Paintworks
		Part	Bumper			Part	Bumper
87		Position	Front	88		Position	Front
		Damages	Scratched			Damages	Scratched
89		Severity	-	90		Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Lumsum Paintworks
91		Part	Exterior door mirror shell	92		Part	Door
		Position	Front left			Position	Front left
93		Damages	Scratched	94		Damages	Scratched
		Severity	-			Severity	-
95		Repair mode	For info	96		Repair mode	Lumsum Paintworks
		Part	Bumper			Part	Bumper
97		Position	Front	98		Position	Front
		Damages	Scratched			Damages	Scratched
99		Severity	-	100		Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Lumsum Paintworks

11		Part Position Damages Severity Repair mode	Headlight Back right Broken - Lumpsum replacement
12		Part Position Damages Severity Repair mode	Headlight Back right Broken - Lumpsum replacement
13		Part Position Damages Severity Repair mode	Wing Back right Dented - For info
14		Part Position Damages Severity Repair mode	Wheel arch trim Back right Scratched - For info
15		Part Position Damages Severity Repair mode	Door moulding Back right Scratched - For info
16		Part Position Damages Severity Repair mode	Door sill Back right Scratched - Lumsum Paintworks
17		Part Position Damages Severity Repair mode	Fabric door lining Back right Dent & Chips - Lumpsum repair
18		Part Position Damages Severity Repair mode Polish all car	Other bodywork - Scratched - Polishing
19		Part Position Damages Severity Repair mode	Windscreen Front Stone impact - Smart Repair
20		Part Position Damages Severity Repair mode	Door sill Front right Dented - Lumpsum repair