


DEKRA Automotive Solutions

Vehicle details

VIN	YV1PZA8U4 K1078176	Brand	VOLVO	Maintenance date	22/11/2024
Licence Plate	WMP324	Model	V90Kombi-2016	Maintenance mileage	150 003 km
Registration date	14/12/2018	Year	2018	Exterior Color	Other
Odometer	162 236 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	16/09/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Refill emergency kit	✓
Load cover	✓
Towing hook	✓

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Spare key	✓
Key	✓
Remote key	✓

DEKRA Automotive Solutions

Tyres

Pirelli 235/55/18 Y Summer 3.0 mm		Pirelli 235/55/18 Y Summer 3.0 mm	
Pirelli 235/55/18 Y Summer 2.0 mm		Pirelli 235/55/18 Y Summer 2.0 mm	

Winter kit

Goodyear 235/55/18 T Winter 8.0 mm		Goodyear 235/55/18 T Winter 8.0 mm	
Goodyear 235/55/18 T Winter 8.0 mm		Goodyear 235/55/18 T Winter 8.0 mm	

Damages

1		Part	Aftermarket wheel	2		Part	Aftermarket wheel
		Position	-			Position	-
3		Damages	Scratched	4		Damages	Scratched
		Severity	-			Severity	-
5		Repair mode	Lumpsum replacement	6		Repair mode	Lumpsum replacement
		Part	Bumper			Part	Bumper moulding
7		Position	Front	8		Position	Front
		Damages	Scratched			Damages	Damaged
9		Severity	-	10		Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Smart Repair
		Part	Bumper			Part	Door
		Position	Front left			Position	Front left
		Damages	Scratched			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Lumsum Paintworks
		Part	Exterior door mirror shell			Part	Door
		Position	Front left			Position	Back left
		Damages	Scratched			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Smart Repair			Repair mode	For info
		Part	Fabric seat			Part	Tailgate / Boot door
		Position	Front left			Position	Back
		Damages	Damaged			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Smart Repair			Repair mode	Lumsum Paintworks
		Part	Door sill			Part	Tailgate / Boot door
		Position	Back left			Position	Back
		Damages	Scratched			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Lumsum Paintworks

11



● ●

Part	Headlight
Position	Back right
Damages	Broken
Severity	-
Repair mode	Lumpsum replacement

12



● ● ● ●

Part	Headlight
Position	Back right
Damages	Broken
Severity	-
Repair mode	Lumpsum replacement

13



● ● ●

Part	Wing
Position	Back right
Damages	Dented
Severity	-
Repair mode	For info

14



● ●

Part	Wheel arch trim
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

15



● ●

Part	Door moulding
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

16



● ● ●

Part	Door sill
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumsum Paintworks

17



● ●

Part	Fabric door lining
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Lumpsum repair

18



● ● ● ● ● ● ● ● ● ●

Part	Other bodywork
Position	-
Damages	Scratched
Severity	-
Repair mode	Polishing
Polish all car	

19



● ●

Part	Windscreen
Position	Front
Damages	Stone impact
Severity	-
Repair mode	Smart Repair

20



● ●

Part	Door sill
Position	Front right
Damages	Dented
Severity	-
Repair mode	Lumpsum repair