

Vehicle details

VIN	YV1UZ25VD L1498600	Brand	VOLVO	Maintenance date	-
Licence Plate	G6-66-SH	Model	XC60 T5 Geartronic Momentum Pro 5d	Maintenance mileage	-
Registration date	22/11/2019	Year	2019	Exterior Color	Blue Metallic
Odometer	34 498 km	Engine size	1969	interior Color	Beige
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	03/04/2026	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------






Generic equipment	Removable element	Technical Document
Automated air-conditioning ✓	Spare wheel kit ✓	Spare key ✓
Cruise control ✓	Load cover ✓	Remote key ✓
Leather ✓		Sat Nav CD ROM Software ✓
GPS system ✓		
Alloy wheel rims ✓		
Automatic Gearbox ✓		
Heating seats ✓		
Electric seats ✓		
Metallic paint ✓		
Central locking ✓		
Electric windows ✓		
Side rails ✓		
Park Distance Control ✓		
Audio System ✓		
Led lighting ✓		

Tyres






Winter kit



Hankook 235/60/18 Winter 7.5 mm  Hankook 235/60/18 Winter 7.5 mm 

Pirelli 235/60/18 Winter 7.0 mm  Pirelli 235/60/18 Winter 7.0 mm

Exterior

<p>1</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Roof	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	<p>2</p>  <p>● ● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scatched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Front	Damages	Scatched	Severity	-	Repair mode	Repair
Part	Roof																						
Position	-																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Bumper																						
Position	Front																						
Damages	Scatched																						
Severity	-																						
Repair mode	Repair																						
<p>3</p>  <p>● ● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Dent & Chips	Severity	-	Repair mode	Repair	<p>4</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Alloy wheel 18"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scatched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Alloy wheel 18"	Position	Front right	Damages	Scatched	Severity	-	Repair mode	For info
Part	Bonnet																						
Position	-																						
Damages	Dent & Chips																						
Severity	-																						
Repair mode	Repair																						
Part	Alloy wheel 18"																						
Position	Front right																						
Damages	Scatched																						
Severity	-																						
Repair mode	For info																						
<p>5</p>  <p>● ● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Improper repair</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Front right	Damages	Improper repair	Severity	-	Repair mode	Repair												
Part	Door																						
Position	Front right																						
Damages	Improper repair																						
Severity	-																						
Repair mode	Repair																						