

INSPECTION REPORT




End Of Contract

GENERAL INFO

File	245659
License plate	1WFT604
Vehicle identification number	YV1UZARV1K1392802
Dossier	2019 010 129
Make	Volvo XC60 D3 150 Momentum
Mileage	180063.00
First registration	23/05/2019
	23/09/2024

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
81	Door Front Left // Smart Repair Medium	N
91	Rocker Panel Left // Smart Repair Medium	N
116	Wing Rear Left // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
184	Wing Rear Right // Repair & Painting	Y
193	Door Rear Right // Painting	Y
257	Front / Towing Cover / Replace	N
664	Polish complete car	Y


Damage Pictures






Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Left // Polish-scratch




Door Rear Right // Painting-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Front Left // Smart Repair Medium-scratch + dent



Bumper Front // Smart Repair Large-scratch + dent



Front / Towing Cover / Replace-missing





Polish complete car-Chemical reaction