



VOLVO XC60: 1YGC581			
Vinnumber:	YV1UZARV1L1611022	Versionname:	D3 Business Luxury Edition
First Registrationdate:	20/08/2020	Fiscalpower:	
Expertise Mileage:	159988	Power Kw:	110
Bodytype:		Parking lot	2201
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Body colour	Black
Fueltype:	Diesel		
Certificate of Conformity	Yes		
Type of rims (mounted)	Aluminium		
Category	Passenger Car		
Registration Certificate Home (BE)	No		
Registration Certificate Car (BE)	Yes		
Maintenance	OK		
Maintenance	+305d		
Options			
Radio multimedia		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Seats electric F L	
Type of GPS storage	HD	Front parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar collapsible
Cruise Control			
Type of climate control	Autom climate control		
Number of keys total	2		
Type of headlighting	Headlighting LED		
Adaptive cruise control			
Type of Lining	Lining leather		
Limited Technical Inspection			
Tyres			
Tyre size RL		235/55 R 19 105 V	
Tyre type FL		Summer	
Tyre type RL		Summer	
Tyre profile depth FR		7.0	
Tyre profile depth RR		7.0	
Tyre make FR		256	
Tyre size FR		235/55 R 19 105 V	
Tyre make RR		256	
Tyre size RR		235/55 R 19 105 V	
Summer tyres:	235/55/19/105 V		
	Fr.L.	Continental: 7 mm	Fr.R. Continental: 7 mm
	Re.L.	Continental: 7 mm	Re.R. Continental: 7 mm
Tyre profile depth FL		7.0	
Tyre make FL		256	
Tyre size FL		235/55 R 19 105 V	
Tyre type FR		Summer	
Tyre profile depth RL		7.0	
Tyre type RR		Summer	
Tyre make RL		256	
Assistance equipment			
Number of charging cables (normal)	0	Jack	Yes
Emergency spare wheel	Yes		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			1389,16
Bonnet, Dent(s), Acceptable			0,00



Windscreen, Crack, Replace	0,00
----------------------------	------



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)	404,88
--	--------



Door FL, Dent(s) and scratch(es), Acceptable	0,00
--	------



Door RL, Dent(s) and scratch(es), Acceptable	0,00
--	------



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)	404,88
--	--------



Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------





Alloy rim RR polished, Scratch(es), Acceptable

0,00



Door RR, Dent(s) and scratch(es), Repair and paint (complete)

579,40



Door FR, Scratch(es), Acceptable

0,00



Alloy rim FR polished, Scratch(es), Acceptable

0,00



Wing FR, Scratch(es), Acceptable

0,00

