



VOLVO XC60: 1YGC581				
Vinnumber:	YV1UZARV1L1611022	Versionname:	D3 Business Luxury Edition	
First Registrationdate:	20/08/2020	Fiscalpower:		
Expertise Mileage:	159988	Power Kw:	110	
Bodytype:		Body colour	Black	
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	2201	
Fueltype:	Diesel			
Maintenance	OK			
Maintenance	+305d			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Seats electric F L		
Cruise Control		Luggage cover		
Steering wheel multifunctional		Front parking sensors		
Seats F heated		Rear parking sensors		
Radio multimedia		Type of Tow bar	Tow bar collapsible	
Type of headlighting	Headlighting LED			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Adaptive cruise control				
Type of GPS storage	HD			
Limited Technical Inspection				
Tyres				
Summer tyres:	235/55/19/105 V			
	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				235/55 R 19 105 V
Tyre size FR				235/55 R 19 105 V
Tyre size RL				235/55 R 19 105 V
Tyre size RR				235/55 R 19 105 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256
Assistance equipment				
Emergency spare wheel	Yes	Jack		Yes
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT				1389,16
Bonnet, Dent(s), Acceptable				0,00



Windscreen, Crack, Replace	0,00
----------------------------	------



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)	404,88
--	--------



Door FL, Dent(s) and scratch(es), Acceptable	0,00
--	------



Door RL, Dent(s) and scratch(es), Acceptable	0,00
--	------



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)	404,88
--	--------



Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------





Alloy rim RR polished, Scratch(es), Acceptable

0,00



Door RR, Dent(s) and scratch(es), Repair and paint (complete)

579,40



Door FR, Scratch(es), Acceptable

0,00



Alloy rim FR polished, Scratch(es), Acceptable

0,00



Wing FR, Scratch(es), Acceptable

0,00

