



VOLVO XC60: 1YTV143

Vinnnummer:	YV1UZBFVDM1773341	Versionname:	T6 Recharge Geartronic Inscription Expr.
First Registrationdate:	11/12/2020	Fiscalpower:	
Expertise Mileage:	61808	Power Kw:	251
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2425
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Sun Roof electric	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar collapsible
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Degree of wear

235/60/16/107 V				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/60 R 16 107 V
Tyre size FR				235/60 R 18 107 V
Tyre size RL				235/60 R 16 107 V
Tyre size RR				235/60 R 18 107 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Total cost ex VAT	3653,11
Interior, Smell, Ozone treatment	208,23



Bumper F, Scratch(es), Spot repair 144,58



Bumper spoiler F, Scratch(es), Spot repair 144,58



Windscreen, Scratch(es), Replace 699,56



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 199,04



Boot carpet, Chemical polution, Cleaning 28,43



Bumper R, Crack, Replace and paint 1322,43



Rear window, Scratch(es), Replace 707,22



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 199,04



Wing RR, Scratch(es), Polish

0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable

0,00



Alloy rim FR polished, Scratch(es), Acceptable

0,00

