



Volvo XC60 (KKL): 2BJV628

Vinnumber:	YV1UZBFVDN1996350	Versionname:	XC60 Inscription 2.0T6 Recharge 340pk/cv 5p AWD Geartronic
First Registrationdate:	13/12/2021	Fiscalpower:	
Expertise Mileage:	155157	Power Kw:	185
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	in 9919 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	235/55/19/105 V			
Summer tyres:	Fr.L.	Semperit: 6 mm	Fr.R.	Semperit: 6 mm
	Re.L.	Semperit: 6 mm	Re.R.	Semperit: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				235/55 R 19 105 V
Tyre size FR				235/55 R 19 105 V
Tyre size RL				235/55 R 19 105 V
Tyre size RR				235/55 R 19 105 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2477
Tyre make FR				2477
Tyre make RL				2477
Tyre make RR				2477

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		

Seat cover FL, Worn, Acceptable



Bonnet, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Acceptable



Charging cable (normal), Missing, Check



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)

