

DEKRA Automotive Solutions

Vehicle details

VIN	YV1UZH1V4 P1219736	Brand	VOLVO	Maintenance date	02/07/2025
Licence Plate	GG98C	Model	XC60-2017	Maintenance mileage	116 454 km
Registration date	16/08/2022	Year	2022	Exterior Color	Other
Odometer	122 651 km	Engine size	-	interior Color	
Fuel	Petrol	Body Type	SUV CrossOver	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	8		

Inspection Details

Inspection date	30/09/2025	Inspection loc.	Eurotransport Kungsängen		
					
					
					

Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Bluetooth	✓
Sliding roof	✓
Panoramic roof	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Refill emergency kit	✓
Load cover	✓
Towing hook	✓

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Spare key	✓
Charging kit	✓

DEKRA Automotive Solutions

Tyres

Michelin 235/60/18 H All seasons 5.0 mm		Michelin 235/60/18 H All seasons 5.0 mm	
Michelin 235/60/18 H All seasons 4.0 mm		Michelin 235/60/18 H All seasons 4.0 mm	

Winter kit

Nokian 235/60/18 T Winter 9.0 mm		Nokian 235/60/18 T Winter 9.0 mm	
Nokian 235/60/18 T Winter 9.0 mm		Nokian 235/60/18 T Winter 9.0 mm	

Damages

1



Part	Complete service track record
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum

2



Part	Locking wheel nut
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

3



Part	Other technic
Position	-
Damages	Defective
Severity	-
Repair mode	For info
SoS ecall in need of service	

4



Part	Aftermarket wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

5



Part	Battery
Position	-
Damages	Defective
Severity	-
Repair mode	For info
booster required	

6



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Lumsum Paintworks paint cracked

7



Part	Door
Position	Front left
Damages	Dented
Severity	-
Repair mode	For info

8



Part	Tailgate / Boot door
Position	-
Damages	Scratched
Severity	-
Repair mode	For info