

DEKRA Automotive Solutions

Vehicle details

VIN	YV1UZH1V7 P1278795	Brand	VOLVO	Maintenance date	06/10/2025
Licence Plate	BSH28A	Model	XC60-2017	Maintenance mileage	42 112 km
Registration date	28/11/2022	Year	2022	Exterior Color	Other
Odometer	42 744 km	Engine size	-	interior Color	
Fuel	Petrol	Body Type	SUV CrossOver	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	8		

Inspection Details

Inspection date	20/10/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Bluetooth	✓
Sliding roof	✓
Panoramic roof	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Refill emergency kit	✓
Load cover	✓
Towing hook	✓

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Spare key	✓
Charging kit	✓
Type 2 charging cables	✓

DEKRA Automotive Solutions

Tyres

Michelin 235/55/19 H All seasons 6.0 mm		Michelin 235/55/19 H All seasons 6.0 mm	
Michelin 235/55/19 H All seasons 6.0 mm		Michelin 235/55/19 H All seasons 6.0 mm	

Winter kit

Michelin 235/60/18 T Winter 9.0 mm		Michelin 235/60/18 T Winter 9.0 mm	
Michelin 235/60/18 T Winter 9.0 mm		Michelin 235/60/18 T Winter 9.0 mm	

Damages

1



Part

Aftermarket wheel

Position

-

Damages

Scratched

Severity

-

Repair mode

For info

2



Part

Bumper

Position

Front

Damages

Scratched

Severity

-

Repair mode

Lumsum Paintworks

3



Part

Registration plates

Position

Front

Damages

Dented

Severity

-

Repair mode

Lumpsum replacement

4



Part

Wing

Position

Front left

Damages

Scratched

Severity

-

Repair mode

For info

5



Part

Door

Position

Back left

Damages

Dented

Severity

-

Repair mode

For info

6



Part

Alloy wheel

Position

Back left

Damages

Scratched

Severity

-

Repair mode

For info

7



Part

Bumper

Position

Back

Damages

Scratched

Severity

-

Repair mode

Lumsum Paintworks

8



Part

Door moulding

Position

Front right

Damages

Scratched

Severity

-

Repair mode

For info

9



Part

Alloy wheel

Position

Front right

Damages

Scratched

Severity

-

Repair mode

Lumpsum replacement

10



Part

Windscreen

Position

-

Damages

Broken

Severity

-

Repair mode

Lumpsum replacement