



VOLVO C40: GD-112-VW

Vinnnumber:	YV1XKEDVEN2001538	Versionname:	
First Registrationdate:	28/12/2021	Fiscalpower:	
Expertise Mileage:	67116	Power Kw:	
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Electric	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total:	2	Sun Roof electric
Number keys remote:	2	Luggage cover
GPS big screen color:		Rear view camera
GPS storage:		
GPS storage:	HD	

Degree of wear

235/50/19/108 W				
Winter tyres:	Fr.L.	Goodyear: 25%	Fr.R.	Goodyear: 30%
	Re.L.	Goodyear: 20%	Re.R.	Goodyear: 20%
Tyre profile depth FL				6.5
Tyre profile depth FR				6.3
Tyre profile depth RL				7.0
Tyre profile depth RR				6.8
Tyre size FL				235/50 R 19 108 W
Tyre size FR				235/50 R 19 108 W
Tyre size RL				235/50 R 19 108 W
Tyre size RR				235/50 R 19 108 W
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	No	Compressor	No
Seat cover FR, Stain, Cleaning			



Seat cover FL, Stain, Cleaning



Tyres, No damage, Acceptable



Compressor, Missing, Repair/replace (lump sum)



Tyre repair kit, Missing, Repair/replace (lump sum)

