



VOLVO XC40: 1VKH320

Vinnnummer:	YV1XZ72B1K2101303	Versionname:	D3 XC40
First Registrationdate:	4/12/2018	Fiscalpower:	
Expertise Mileage:	81875	Power Kw:	110
Bodytype:		Parking lot:	3208
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Body colour:	Grey
Fueltype:	Diesel		
Certificate of Conformity:	Yes		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		
Registration Certificate Home (BE):	No		
Registration Certificate Car (BE):	Yes		
Maintenance:	NOT OK		

Options

Steering wheel multifunctional		Luggage cover	
Radio multimedia		Rear parking sensors	
Seats F heated		Front parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Cruise Control			
Type of climate control	Autom climate control		
Type of headlighting	Headlighting LED		
Number of keys total	2		
Type of Lining	Lining fabrics		

Limited Technical Inspection

Degree of wear

Tyre size RL	235/60 R 17 102 H
Tyre type FL	All seasons
Tyre type RL	All seasons
Tyre profile depth FR	5.0
Tyre profile depth RR	5.0
Tyre make FR	259
Tyre size FR	235/60 R 17 102 H
Tyre make RR	259
Tyre size RR	235/60 R 17 102 H

235/60/17/102 H			
Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Tyre profile depth FL	5.0
Tyre make FL	259
Tyre size FL	235/60 R 17 102 H
Tyre type FR	All Seasons
Tyre profile depth RL	5.0
Tyre make RL	259
Tyre type RR	All Seasons

Assistance equipment

Number of charging cables (normal)	0	Compressor	Yes
Number of charging cables (rapid charge)	0		
Repair kit	Yes		

Total cost ex VAT	359,53
Seat cover FL, Stain, Cleaning	28,43



Seat cover R, Stain, Cleaning

28,43



Seat cover FR, Stain, Cleaning

28,43



Service, Maintenance, Check

0,00



Engine insulation, Damaged, Acceptable

0,00



Bonnet, Dent(s), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Alloy rim RL, Scratch(es), Acceptable

0,00



Door FL, Scratch(es), Acceptable

0,00



Door RL, Scratch(es), Acceptable

0,00



Wing RL, Scratch(es), Spot repair

144,58



Bumper R, Scratch(es), Acceptable 0,00



Tailgate / Boot, Scratch(es), Acceptable 0,00



Bumper moulding R, Scratch(es), Acceptable 0,00



Door RR, Scratch(es), Acceptable 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 129,66



Wing FR, Scratch(es), Acceptable 0,00

