



**VOLVO XC40: 1VKH320**

Vinnnumber:	<b>YV1XZ72B1K2101303</b>	Versionname:	<b>D3 XC40</b>
First Registrationdate:	<b>4/12/2018</b>	Fiscalpower:	
Expertise Mileage:	<b>81854</b>	Power Kw:	<b>110</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>4708</b>
Fueltype:	<b>Diesel</b>		
Maintenance:	<b>NOT OK</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	<b>No Tow bar</b>
Radio multimedia:			
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Degree of wear**

235/60/17/102 H				
Summer tyres:	Fr.L.	<b>Goodyear: 6 mm</b>	Fr.R.	<b>Goodyear: 6 mm</b>
	Re.L.	<b>Goodyear: 8 mm</b>	Re.R.	<b>Goodyear: 8 mm</b>
Tyre profile depth FL				<b>6.0</b>
Tyre profile depth FR				<b>6.0</b>
Tyre profile depth RL				<b>8.0</b>
Tyre profile depth RR				<b>8.0</b>
Tyre size FL				<b>235/60 R 17 102 H</b>
Tyre size FR				<b>235/60 R 18 102 H</b>
Tyre size RL				<b>235/60 R 17 102 H</b>
Tyre size RR				<b>235/60 R 17 102 H</b>
Tyre type FL				<b>All seasons</b>
Tyre type FR				<b>All Seasons</b>
Tyre type RL				<b>All seasons</b>
Tyre type RR				<b>All Seasons</b>
Tyre make FL				<b>259</b>
Tyre make FR				<b>259</b>
Tyre make RL				<b>259</b>
Tyre make RR				<b>259</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

<b>Total cost ex VAT</b>	<b>258,30</b>
<b>Seat cover FL, Stain, Cleaning</b>	<b>28,43</b>



Service, Maintenance, Check

0,00



Seat cover R, Stain, Cleaning

28,43



Seat cover FR, Stain, Cleaning

28,43



Engine insulation, Damaged, Acceptable

0,00



Bonnet, Dent(s), Acceptable

0,00



Alloy rim RL, Scratch(es), Acceptable

0,00



Wing FL, Scratch(es), Spot repair

144,58



Door FL, Scratch(es), Acceptable

0,00



Door RL, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Boot carpet, Dirty, Cleaning

28,43



Tailgate / Boot, Scratch(es), Acceptable

0,00



Bumper moulding R, Scratch(es), Acceptable

0,00



Door RR, Scratch(es), Acceptable

0,00



Alloy rim FR, Scratch(es), Acceptable

0,00

