



VOLVO XC40: 1YEV433

Vinnnumber:	YV1XZ72V1M2402904	Versionname:	D3 Inscription
First Registrationdate:	7/08/2020	Fiscalpower:	
Expertise Mileage:	188164	Power Kw:	110
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1724
Fueltype:	Diesel		
Maintenance:	OK		
Maintenance:	1814.0		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	3	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Degree of wear

	235/50/19/103 V			
Summer tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				235/50 R 19 103 V
Tyre size FR				235/50 R 19 103 V
Tyre size RL				235/50 R 19 103 V
Tyre size RR				235/50 R 19 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				257
Tyre make FR				257
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	1599,04
Engine insulation, Damaged, Replace:	206,06



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)

404,88



Bumper moulding F, Deformed / Strained, Replace

221,59



Bumper spoiler F, Scratch(es), Acceptable

0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

199,04



Step L, Scratch(es), Acceptable

0,00



Boot carpet, Dirty, Cleaning

28,43



Bumper R, Scratch(es), Acceptable

0,00



Reflector, Broken, Replace

140,96



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

199,04



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

199,04

