



**VOLVO XC40: 1YPH484**

Vinnumber:	<b>YV1XZ72V1M2434304</b>	Versionname:	<b>D3 Momentum Pro</b>
First Registrationdate:	<b>26/10/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>132604</b>	Power Kw:	<b>110</b>
Bodytype:		Parking lot	<b>2505</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted)	<b>Aluminium</b>
Transmission:		Body colour	<b>Black</b>
Fueltype:	<b>Diesel</b>		
Certificate of Conformity	<b>Yes</b>		
Type of rims (mounted)	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Registration Certificate Home (BE)	<b>No</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio multimedia		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Type of GPS	<b>GPS big screen color</b>	Sun Roof electric	
Cruise Control		Front parking sensors	
Type of climate control	<b>Autom climate control</b>	Panoramic roof	
Number of keys total	<b>3</b>	Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting LED</b>		
Type of Lining	<b>Lining leather</b>		

**Limited Technical Inspection**

**Tyres**

Tyre size RL	<b>235/55 R 18 100 V</b>
Tyre type FL	<b>Summer</b>
Tyre type RL	<b>Summer</b>
Tyre profile depth FR	<b>3.0</b>
Tyre profile depth RR	<b>3.0</b>
Tyre make FR	<b>2477</b>
Tyre size FR	<b>235/55 R 18 100 V</b>
Tyre make RR	<b>2477</b>
Tyre size RR	<b>235/55 R 18 100 V</b>

<b>235/55/18/100 V</b>				
Summer tyres:	Fr.L.	<b>Semperit: 3 mm</b>	Fr.R.	<b>Semperit: 3 mm</b>
	Re.L.	<b>Semperit: 3 mm</b>	Re.R.	<b>Semperit: 3 mm</b>

Tyre profile depth FL	<b>3.0</b>
Tyre make FL	<b>2477</b>
Tyre size FL	<b>235/55 R 18 100 V</b>
Tyre type FR	<b>Summer</b>
Tyre profile depth RL	<b>3.0</b>
Tyre type RR	<b>Summer</b>
Tyre make RL	<b>2477</b>

**Assistance equipment**

Number of charging cables (normal)	<b>0</b>	Compressor	<b>Yes</b>
Number of charging cables (rapid charge)	<b>0</b>		
Repair kit	<b>Yes</b>		

<b>Total cost ex VAT</b>	<b>129,66</b>
--------------------------	---------------

<b>Interior, Worn, Acceptable</b>	<b>0,00</b>
-----------------------------------	-------------



Bumper F, Scratch(es), Acceptable 0,00



Bumper spoiler F, Scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), Repair and paint (complete) 129,66



Step L, Dent(s) and scratch(es), Acceptable 0,00



Wing trim FL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Alloy rim FR, Scratch(es), Acceptable 0,00



Step R, Scratch(es), Acceptable 0,00

