


Vehicle details

VIN	YV1XZBBVF L2296980	Brand	VOLVO	Maintenance date	-
Licence Plate	H6-89-HS	Model	XC40 T5 Twin Engine Geartronic Momentum Pro 5d	Maintenance mileage	-
Registration date	13/02/2020	Year	2020	Exterior Color	White Solid
Odometer	119 690 km	Engine size	1477	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	-	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	04/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Wireless charger	✗
Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓

Technical Document

Spare key	✗
User manual	✓
Warranty booklet	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 235/55/18 Summer 5.0 mm



Continental 235/55/18 Summer 5.0 mm



Continental 235/55/18 Summer 6.0 mm

Continental 235/55/18 Summer 5.0 mm


Exterior

3



Part	Exterior door mirror shell
Position	Front left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

5



Part	Wing moulding
Position	Back right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

6



Part	Alloy wheel 18"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

7



Part	Door
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

8



Part	Bumper
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair


9



Part	Windscreen
Position	-
Damages	Broken
Severity	-
Repair mode	Replace

Interior damage

2



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

4



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

Others

1



Part	Wireless charger
Position	-
Damages	Missing
Severity	-
Repair mode	For info