

Vehicle details

VIN	YV1XZBBVF L2343727	Brand	VOLVO	Maintenance date	-
Licence Plate	J5-28-DZ	Model	XC40 T5 Twin Engine Plug-in Hybr Momentum Pro 5d	Maintenance mileage	-
Registration date	17/07/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	69 555 km	Engine size	1477	interior Color	Grey
Fuel	Plugin-Hybrid Benzin	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	25/08/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Sliding roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Wireless charger	✗
Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 235/55/18 Summer 5.5 mm



Pirelli 235/55/18 Summer 5.5 mm



Continental 235/55/18 Summer 4.0 mm

Continental 235/55/18 Summer 4.0 mm


Exterior

2



Part	Wing
Position	Front left
Damages	Misaligned
Severity	-
Repair mode	Adjust

6



Part	Door
Position	Back right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

7



Part	Wing
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

8



Part	Bumper
Position	Front left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

9



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

10



Part	Roofrail
Position	Right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

11



Part	Unpainted bumper
Position	Front left
Damages	Misaligned
Severity	-
Repair mode	Adjust

Interior damage

3



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

4



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

5



Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Replace

Others

1		Part	Wireless charger
		Position	-
		Damages	Missing
		Severity	-
		Repair mode	For info