



Volvo XC 40: 2BDN696

Vinnumber:	YV1XZBBVFN2686633	Versionname:	
First Registrationdate:	13/10/2021	Fiscalpower:	
Expertise Mileage:	32653	Power Kw:	
Bodytype:		Parking lot	2328
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Body colour	Grey
Fueltype:	Hybrid Petrol		
Certificate of Conformity	Yes		
Type of rims (mounted)	Aluminium		
Category	Passenger Car		
Registration Certificate Home (BE)	No		
Registration Certificate Car (BE)	Yes		

Options

Radio multimedia		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Type of GPS	GPS big screen color	Front parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Type of climate control	Autom climate control		
Number of keys total	2		
Type of headlighting	Headlighting LED		
Type of Lining	Lining fabrics		

Limited Technical Inspection

Tyres

Tyre size RL	235/55 R 18 100 V
Tyre type FL	Summer
Tyre type RL	Summer
Tyre profile depth FR	4.0
Tyre profile depth RR	4.0
Tyre make FR	261
Tyre size FR	235/55 R 18 100 V
Tyre make RR	261
Tyre size RR	235/55 R 18 100 V

235/55/18/100 V

Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre make FL				261
Tyre size FL				235/55 R 18 100 V
Tyre type FR				Summer
Tyre profile depth RL				4.0
Tyre type RR				Summer
Tyre make RL				261

Assistance equipment

Number of charging cables (normal)	0	Compressor	Yes
Number of charging cables (rapid charge)	1		
Repair kit	Yes		

Total cost ex VAT	199,04
-------------------	--------

Interior covering A pillar R, Scratch(es), Acceptable	0,00
---	------



Bumper F, Scratch(es), Acceptable 0,00



Tailgate / Boot, Dent(s), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 199,04



Wing RR, Dent(s), Acceptable 0,00

