

Inspection Protocol

VOLVO XC40 T4 TWEN DCT, 211HK, 2023

Vehicle information

| | | | |
|-----------------------------|-----------|--------------------------------------|--------------------------|
| License plate | GWA11C | Inspected by | R.A. |
| Year model | 2023 | Date of inspection | 2025-11-27 |
| Manuf. year/month | 2022-12 | City | Falkenberg |
| First day in traffic | 2022-12 | Keys | 2 |
| Colour | Vit | Service book | Ja |
| Mileage | 68 880 km | Latest service | 2024-12-11 |
| Fuel | Elhybrid | Mileage at the latest service | 49 210 km |
| Transmission | Automat | Summer tires | 19" alu-fälg 5/6/6/5 |
| Engine effect | 155 kW | Winter tires | alu-fälg odubbat 8/8/8/8 |

Damages

| Location | Damage | Comments | Costs excluding VAT |
|-----------------------|-------------------|--------------------------------|---------------------|
| Other, Other | Other | Insteg vb liten buckla | - |
| Skärm , Rear right | Smart repair | Liten buckla | 70 € |
| Bumper, Front | Smart repair | | 70 € |
| Glass, Windshield | Stenskott/Spricka | | - |
| Service, Not serviced | Missad service | | 360 € |
| Other, Other | Other | Bristfälligt ifylld servicebok | - |
| Rims, Aluminum rim | Damage | Vinterfälg | 220 € |

Total excl. VAT 720 €

Images

[See all images in large format](#)











































