



Volvo XC40: L758HF

Vinnnummer:	YV1XZBWVFM2603118	Versionname:	XC40 T4 Recharge 155kW Inscription Expression automaat
First Registrationdate:	26/05/2021	Fiscalpower:	
Expertise Mileage:	165720	Power Kw:	95
Bodytype:		Body colour:	Black Stone solid
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	425
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Central consol F
GPS		Luggage cover
Autom climate control		Headlights Xenon/LED/Laser
Windows electric F		Front parking sensors
Radio multimedia		Rear parking sensors

Degree of wear

	235/50/19/99 H			
Winter tyres:	Fr.L.	Bridgestone: 6,1 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 6,2 mm	Re.R.	Bridgestone: 6,2 mm
Tyre profile depth FL				6.1
Tyre profile depth FR				6.0
Tyre profile depth RL				6.2
Tyre profile depth RR				6.2
Tyre size FL				235/50 R 19 99 H
Tyre size FR				235/50 R 19 99 H
Tyre size RL				235/50 R 19 99 H
Tyre size RR				235/50 R 19 99 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Armrest F M, Worn, Replace



Door RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Wheel arch cover RL, Scratch(es), Replace



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Door RR, Scratch(es), Polish



Charging cable (normal), Missing, Replace



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bumper corner RR, Scratch(es), Repair and paint (complete)

Bumper corner KK, Scratch(es), Repair and paint (complete)



Bumper corner RL, Scratch(es), Repair and paint (complete)

