



Volvo XC40: K817FS

Vinnumber:	VV1XZEDVEM2492233	Versionname:	XC40 P8 AWD Recharge 300kW/ 78kWh
First Registrationdate:	9/12/2020	Fiscalpower:	
Expertise Mileage:	146994	Power Kw:	300
Bodytype:		Body colour	Sage Green metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	1151
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	3	Telephone equipment
Number keys remote	3	Lining semi-leather
GPS		Lining Alcantara
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Rear parking sensors

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	255 / 15 / 19 / 104 / V / Aluminium	5,7 mm	Continental	Summer
	Right	255 / 15 / 19 / 104 / V / Aluminium	5,3 mm	Continental	Summer
Rear	Left	255 / 15 / 19 / 104 / V / Aluminium	4,0 mm	Continental	Summer
	Right	255 / 15 / 19 / 104 / V / Aluminium	4,0 mm	Continental	Summer

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

User's manual, Missing, Replace

No pictures to display

Outside rear-view mirror housing L, Scratch(es), Replace and paint



Bumper F, Scratch(es), Repair and paint (complete)



Bumper spoiler F, Dent(s), Replace



Bonnet, Chemical polution, Repair and paint (complete)



Windscreen, Crack, Replace



Bumper moulding F, Scratch(es), Replace and paint



Door RR, Scratch(es), Repair and paint (complete)



Wheel arch cover RR, Scratch(es), Replace



Door trim RR, Scratch(es), Replace



Door FR, Bad repair, Repair and paint (complete)



Boot cover, Broken, Replace



Bumper corner RL, Scratch(es), Repair and paint (complete)



Roof, Scratch(es), Repair and paint (complete)

