

## Vehicle details

|                   |                    |              |                                  |                           |                |
|-------------------|--------------------|--------------|----------------------------------|---------------------------|----------------|
| VIN               | YV1XZEDVE M2501987 | Brand        | VOLVO                            | Maintenance date          | -              |
| Licence Plate     | K8-54-GL           | Model        | XC40 Recharge P8 AWD R-Design 5d | Maintenance mileage       | -              |
| Registration date | 28/12/2020         | Year         | 2020                             | Exterior Color            | Black Metallic |
| Odometer          | 127 970 km         | Engine size  | -                                | interior Color            | Black          |
| Fuel              | Electric           | Body Type    | -                                | Next technical inspection | -              |
| Seats             | -                  | Transmission | Automatic                        | CO2                       | -              |
| Doors             | 5                  | Gears        | -                                |                           |                |

## Inspection Details

|                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                       |                                                                                       |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Inspection date                                                                     | 02/09/2025                                                                          | Inspection loc.                                                                     | Ayvens Veghel                                                                       |                                                                                       |                                                                                       |
|    |    |    |    |    |    |
|   |   |   |   |   |   |
|  |  |  |  |  |  |
|  |  |  |  |                                                                                       |                                                                                       |

## Generic equipment

|                            |   |
|----------------------------|---|
| Automated air-conditioning | ✓ |
| Cruise control             | ✓ |
| GPS system                 | ✓ |
| Alloy wheel rims           | ✓ |
| Automatic Gearbox          | ✓ |
| Heating seats              | ✓ |
| Electric seats             | ✓ |
| Metallic paint             | ✓ |
| Central locking            | ✓ |
| Electric windows           | ✓ |
| Mixed upholstery           | ✓ |
| Side rails                 | ✓ |
| Park Distance Control      | ✓ |
| Audio System               | ✓ |
| Led lighting               | ✓ |

## Removable element

|                   |   |
|-------------------|---|
| Rear parcel shelf | ✓ |
| Vehicle charger   | ✓ |
| Wireless charger  | ✗ |


## Technical Document

|                         |   |
|-------------------------|---|
| User manual             | ✓ |
| Warranty booklet        | ✓ |
| Spare key               | ✓ |
| Key                     | ✓ |
| Remote key              | ✓ |
| Sat Nav CD ROM Software | ✓ |

## Tyres

|                                     |                                                                                   |                                     |                                                                                    |
|-------------------------------------|-----------------------------------------------------------------------------------|-------------------------------------|------------------------------------------------------------------------------------|
| Hankook 235/50/19 Summer 6.5 mm     |  | Hankook 235/50/19 Summer 6.0 mm     |  |
| Continental 255/45/19 Summer 4.5 mm |  | Continental 255/45/19 Summer 4.0 mm |   |

## Exterior

|    |                                                                                     |                                                                                                                     |    |                                                                                      |                                                                                                                     |
|----|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|----|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|
| 2  |    | Part: Wing<br>Position: Front left<br>Damages: Chemical deposit<br>Severity: -<br>Repair mode: Lumpsum repair       | 3  |    | Part: Wing<br>Position: Back left<br>Damages: Chemical deposit<br>Severity: -<br>Repair mode: Lumpsum repair        |
| 4  |   | Part: Wing<br>Position: Back right<br>Damages: Dent & Chips<br>Severity: Diameter (mm) > 20<br>Repair mode: Repair  | 5  |   | Part: Alloy wheel 19"<br>Position: Back right<br>Damages: Scratched<br>Severity: -<br>Repair mode: Lumpsum repair   |
| 6  |  | Part: Alloy wheel 19"<br>Position: Front right<br>Damages: Scratched<br>Severity: -<br>Repair mode: Lumpsum repair  | 7  |  | Part: Bonnet badge<br>Position: -<br>Damages: Chemical deposit<br>Severity: -<br>Repair mode: For info              |
| 8  |  | Part: Spoiler<br>Position: Front<br>Damages: Chemical deposit<br>Severity: -<br>Repair mode: Lumpsum repair         | 9  |  | Part: Bonnet<br>Position: -<br>Damages: Chemical deposit<br>Severity: -<br>Repair mode: Lumpsum repair              |
| 10 |  | Part: Roof<br>Position: -<br>Damages: Chemical deposit<br>Severity: -<br>Repair mode: Lumpsum repair                | 11 |  | Part: Roof post A/B/C<br>Position: Right<br>Damages: Chemical deposit<br>Severity: -<br>Repair mode: Lumpsum repair |
| 12 |  | Part: Roof wind deflector<br>Position: -<br>Damages: Chemical deposit<br>Severity: -<br>Repair mode: Lumpsum repair |    |                                                                                      |                                                                                                                     |

## Others

|   |                                                                                   |             |                  |
|---|-----------------------------------------------------------------------------------|-------------|------------------|
| 1 |  | Part        | Wireless charger |
|   |                                                                                   | Position    | -                |
|   |                                                                                   | Damages     | Missing          |
|   |                                                                                   | Severity    | -                |
|   |                                                                                   | Repair mode | For info         |