


Vehicle details

VIN	YV1XZEDVE M2577992	Brand	VOLVO	Maintenance date	-
Licence Plate	L1-36-BF	Model	XC40 Recharge P8 AWD 5d	Maintenance mileage	-
Registration date	16/04/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	137 118 km	Engine size	-	interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	17/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Sliding roof	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✗

Technical Document

Spare key	✓
Key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 235/50/19 Summer 4.0 mm



Continental 235/50/19 Summer 4.0 mm



Continental 255/45/19 Summer 4.0 mm

Continental 255/45/19 Summer 3.0 mm

Exterior

2



Part	Wing
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair

3



Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

4



Part	Alloy wheel 19"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

5



Part	Bumper
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Repair

6



Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

7



Part	Door
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

8



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

9



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

10



Part	Unpainted bumper
Position	Front right
Damages	Misaligned
Severity	-
Repair mode	Adjust

Others

1



Part	Wireless charger
Position	-
Damages	Missing
Severity	-
Repair mode	For info