


Vehicle details

VIN	YV1XZEFV3 P2932741	Brand	VOLVO	Maintenance date	-
Licence Plate	R4-50-GT	Model	XC40 Recharge Pure Electric Ultimate 5d	Maintenance mileage	-
Registration date	01/09/2022	Year	2022	Exterior Color	White Pearl
Odometer	179 635 km	Engine size	-	interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	03/04/2026	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Sliding roof	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✗





Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓


Tyres

Pirelli 235/50/19 Summer 3.0 mm		Pirelli 235/50/19 Summer 3.0 mm	
Continental 255/45/19 Summer 4.0 mm		Continental 255/45/19 Summer 3.0 mm	

Exterior

<p>2</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Step plate</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Step plate	Position	Front left	Damages	Dent & Chips	Severity	-	Repair mode	For info	<p>3</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Wing	Position	Back right	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Step plate																						
Position	Front left																						
Damages	Dent & Chips																						
Severity	-																						
Repair mode	For info																						
Part	Wing																						
Position	Back right																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
<p>4</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Back right	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	<p>5</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Bumper obturator</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Bumper obturator	Position	Front	Damages	Missing	Severity	-	Repair mode	Replace
Part	Door																						
Position	Back right																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
Part	Bumper obturator																						
Position	Front																						
Damages	Missing																						
Severity	-																						
Repair mode	Replace																						

Others

<p>1</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Wireless charger</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Wireless charger	Position	-	Damages	Missing	Severity	-	Repair mode	For info
Part	Wireless charger										
Position	-										
Damages	Missing										
Severity	-										
Repair mode	For info										