


**GENERAL INFO**

|                 |                                    |
|-----------------|------------------------------------|
| File            | 29949                              |
| License plate   | JJ8437                             |
| VIN             | YV1ZW72VDM2418673                  |
| Dossier         | 2020 168 011 / 217740              |
| Make / Model    | Volvo V60 D3 2.0 150 Momen.Pro Aut |
| Mileage         | 72804                              |
| 1st inscription | 23/11/2020                         |
| Start from      |                                    |
| Available from  | 7/11/2023                          |


**CHECK POINTS**

| Description                     | Number | Pres | Remark |
|---------------------------------|--------|------|--------|
| Original license plate          |        | Y    |        |
| Keys                            | 2      | Y    |        |
| Spare wheel                     |        |      |        |
| Towbar (+keys)                  |        |      |        |
| Certificate of conformity       |        |      |        |
| Registration certificate Part 1 |        |      |        |
| Repair kit                      |        |      |        |
| RunOnFlat                       |        |      |        |
| Charging cable                  |        |      |        |



DAMAGES

There is no chargeable damage

| Id              | Damage                                                 | Dossier nbr | Acceptable damage |
|-----------------|--------------------------------------------------------|-------------|-------------------|
| OTHER DAMAGE(S) |                                                        |             |                   |
| 78              | Side View Mirror Left / Direction Indicator / Replace  |             | Y                 |
| 159             | Rear Bonnet / Rear Window / Replace                    |             | Y                 |
| 222             | Side View Mirror Right // Painting                     |             | Y                 |
| 228             | Side View Mirror Right / Direction Indicator / Replace |             | Y                 |
| 318             | Flat Tyre Kit // Replace                               |             | Y                 |


If any missing items (keys, accessories, car documents, etc.) are invoiced you still can return them to Arval within five business days after reception of the inspection report. You may send this by registered letter to / return it on site ( Arval Belgium NV/SA, Ikaroslaan 99, 1930 Zaventem ) .

## DAMAGE PICTURES




Damage within Renta-norm

### DAMAGE 1




Side View Mirror Right // Painting: E - Scratch




Side View Mirror Right / Direction Indicator / Replace: E - Scratch

### OTHER DAMAGES



Side View Mirror Left / Direction Indicator / Replace: E - Scratch



Rear Bonnet / Rear Window / Replace: E - Scratch



Flat Tyre Kit // Replace: R - Missing