

Inspection Protocol

VOLVO V60 D4

Vehicle information

License plate	ENP65C	Inspected by	E.B.
Year model	2020	Date of inspection	2025-04-11
Manuf. year/month	2020-05	City	Björkvik
First day in traffic	2020-06	Keys	1
Colour	Vit	Service book	Ja
Mileage	150 170 km	Latest service	2023-10-09
Fuel	Diesel	Mileage at the latest service	133 550 km
Transmission	Geartronic	Summer tires	17" alu-fälg 6/6/6/6
Engine effect	140 kW	Winter tires	alu-fälg dubbat 6/6/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Keys	Extra key missing		230 €
Bumper, Rear	Cargo scratches		180 €
Bumper, Front	Wide scratch		300 €

Total excl. VAT	710 €
-----------------	-------

Images

[See all images in large format](#)




























Stötfångare Bak Lastrepör 2 000 kr



Stötfångare Fram Skrap 3 300 kr