



Volvo V60: H777VX

Vinnumber:	YV1ZWBFUDL1398872	Versionname:	V60 T6 2.0 Tw.Engine AWD 250kW Momentum Pro geartronic
First Registrationdate:	11/06/2020	Fiscalpower:	
Expertise Mileage:	153518	Power Kw:	186
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Wheel-drive	Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	701
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	2	Telephone equipment
GPS		Lining semi-leather
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors
		Hook

Degree of wear

235/45/18/98 Y				
Summer tyres:	Fr.L.	Michelin: 4,9 mm	Fr.R.	Michelin: 4,8 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 8 mm
Tyre profile depth FL				4.9
Tyre profile depth FR				4.8
Tyre profile depth RL				6.0
Tyre profile depth RR				8.0
Tyre size FL				235/45 R 18 98 Y
Tyre size FR				235/45 R 18 98 Y
Tyre size RL				235/45 ZR 18 98 Y
Tyre size RR				235/45 ZR 18 98 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Service, Maintenance, Execute



Interior, Stain, Cleaning



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Outer sill R, Scratch(es), Repair and paint (partial)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Replace



Bumper R, Scratch(es), Repair and paint (complete)

Bumper R, scratches, repair and paint (complete)

