


DEKRA Automotive Solutions

Vehicle details

VIN	YV1ZWBFVD M1449131	Brand	VOLVO	Maintenance date	02/09/2024
Licence Plate	MWN93L	Model	T6 AWD Inscript.Rechar.Aut	Maintenance mileage	43 788 km
Registration date	14/04/2021	Year	-	Exterior Color	Other
Odometer	73 725 km	Engine size	-	interior Color	Unknown
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	-	CO2	39
Doors	5	Gears	-		

Inspection Details

Inspection date	19/09/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element


Refill emergency kit	✓
Load cover	✓
Towing hook	✓

Technical Document


Key	✓
Remote key	✓

DEKRA Automotive Solutions



Tyres

Michelin 235/40/19 W Summer 5.0 mm		Michelin 235/40/19 W Summer 5.0 mm	
Michelin 235/40/19 W Summer 6.0 mm		Michelin 235/40/19 W Summer 6.0 mm	

Winter kit

Pirelli 235/45/18 H Winter 8.0 mm		Pirelli 235/45/18 H Winter 8.0 mm	
Pirelli 235/45/18 H Winter 8.0 mm		Pirelli 235/45/18 H Winter 8.0 mm	

Damages

1		Part	Complete service track record	2		Part	Aftermarket wheel
		Position	-			Position	-
3		Damages	Missing	4		Damages	Scratched
		Severity	-			Severity	-
5		Repair mode	Lumpsum	6		Repair mode	Lumpsum replacement
7		Part	Aftermarket wheel	8		Part	Alloy wheel
		Position	-			Position	Front left
9		Damages	Scratched	10		Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Lumpsum replacement			Repair mode	Lumpsum replacement
		Part	Door			Part	Tyre
		Position	Front left			Position	Back left
		Damages	Dented			Damages	Cut
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Lumpsum replacement
		Part	Alloy wheel			Part	Tyre
		Position	Back left			Position	Back right
		Damages	Scratched			Damages	Cut
		Severity	-			Severity	-
		Repair mode	Lumpsum replacement			Repair mode	Lumpsum replacement

DEKRA Automotive Solutions

11



Part

Alloy wheel

Position

Back right

Damages

Scratched

Severity

-

Repair mode

Lumpsum replacement

12



Part

Registration plates

Position

Front

Damages

Dented

Severity

-

Repair mode

Lumpsum replacement

13



Part

Windscreen

Position

Front

Damages

Stone impact

Severity

-

Repair mode

Smart Repair

14



Part

Tyre

Position

Front right

Damages

Cut

Severity

-

Repair mode

Lumpsum replacement

15



Part

Alloy wheel

Position

Front right

Damages

Scratched

Severity

-

Repair mode

Lumpsum replacement

16



Part

Wing

Position

Back left

Damages

Scratched

Severity

-

Repair mode

For info