


DEKRA Automotive Solutions

Vehicle details

VIN	YV1ZWBFVD M1449131	Brand	VOLVO	Maintenance date	02/09/2024
Licence Plate	MWN93L	Model	T6 AWD Inscript.Rechar.Aut	Maintenance mileage	43 788 km
Registration date	14/04/2021	Year	-	Exterior Color	Other
Odometer	73 725 km	Engine size	-	interior Color	Unknown
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	-	CO2	39
Doors	5	Gears	-		

Inspection Details

Inspection date	19/09/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Refill emergency kit	✓
Load cover	✓
Towing hook	✓

Technical Document

Key	✓
Remote key	✓

DEKRA Automotive Solutions


Tyres

Michelin 235/40/19 W Summer 5.0 mm		Michelin 235/40/19 W Summer 5.0 mm	
Michelin 235/40/19 W Summer 6.0 mm		Michelin 235/40/19 W Summer 6.0 mm	

Winter kit

Pirelli 235/45/18 H Winter 8.0 mm		Pirelli 235/45/18 H Winter 8.0 mm	
Pirelli 235/45/18 H Winter 8.0 mm		Pirelli 235/45/18 H Winter 8.0 mm	

Damages

1		Part	Complete service track record	2		Part	Aftermarket wheel
		Position	-			Position	-
3		Damages	Missing	4		Damages	Scratched
		Severity	-			Severity	-
5		Repair mode	Lumpsum	6		Repair mode	Lumpsum replacement
7		Part	Aftermarket wheel	8		Part	Tyre
		Position	-			Position	-
9		Damages	Scratched	10		Damages	Cut
		Severity	-			Severity	-
		Repair mode	Lumpsum replacement			Repair mode	Lumpsum replacement

DEKRA Automotive Solutions

11



Part	Alloy wheel
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

● ●

12



Part	Registration plates
Position	Front
Damages	Dented
Severity	-
Repair mode	Lumpsum replacement

●

13



Part	Windscreen
Position	Front
Damages	Stone impact
Severity	-
Repair mode	Smart Repair

● ●

14



Part	Tyre
Position	Front right
Damages	Cut
Severity	-
Repair mode	Lumpsum replacement

● ● ●

15



Part	Alloy wheel
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

● ●

16



Part	Wing
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

● ●