

Inspection Protocol



VOLVO V60 RECHARGE T6 AWD

Vehicle information

License plate	EYW459	Inspected by	A.A.
Year model	2024	Date of inspection	2025-03-11
Manuf. year/month	2023-11	City	Björkvik
First day in traffic	2023-12	Keys	2
Colour	GRÅ	Service book	Ja
Mileage	20 990 km	Latest service	2024-11-29
Fuel	Elhybrid	Mileage at the latest service	15 830 km
Transmission	Automat	Summer tires	18" alu-fälg 6/6/6/6
Engine effect	257 kW	Winter tires	alu-fälg odubbat 8/8/8/8

Damages

Location	Damage	Comments	Costs excluding VAT
Bumper, Rear	Paint retouch traces		0 €
Recond	Animal hairs	Passagerare sätet	110 €
Glass, Windshield	Chip		20 €
Rims & Tires, Winter	Rim damage 1 wheel	Hf	110 €
Rims & Tires, Winter	Rim damage 1 wheel	Hb	110 €
Rims & Tires, Winter	Rim damage 1 wheel	Vb	110 €
Rims & Tires, Winter	Rim damage 1 wheel	Vf	110 €

Total excl. VAT	570 €
-----------------	-------

Service occasions

1500-MIL

Images

[See all images in large format](#)



















ion
av verkstaden med
innehållet i din
hållsservice enligt

Service Nr. 1

Utförd
km 15837

Datum 2024-11-29

Arbetsorder nr. 669912

Typ av service

Basservice STÄMPEL

Underhållsservice STÄMPEL

Anpassad basservice

VOLVO
Alexander Stojmenovic
Volvo car Kista
tel 08-58000925
alexander.stojmenovic@volvocarretail.se

Intervalltillägg/Övrigt STÄMPEL

Service Nr. 2

Utförd
km

Datum

Arbetsorder nr.

Typ av service

Basservice STÄMPEL

Underhållsservice STÄMPEL

Anpassad basservice STÄMPEL

Intervalltillägg/Övrigt STÄMPEL

Service Nr. 3

Utförd
km

Datum

Arbetsorder nr.

Typ av service

Basservice

Underhållsservice











Stötfångare Bak Lackbättring 50 kr



Rekond Djurhår Passagerare sätet 1 500 kr



Glas Vindruta Stenskott 300 kr



Fälgar & Däck Vinter Fälgskada 1 hjul Hf 1 500 kr



Fälgar & Däck Vinter Fälgskada 1 hjul Hb 1 500 kr



Fälgar & Däck Vinter Fälgskada 1 hjul Vb 1 500 kr



Fälgar & Däck Vinter Fälgskada 1 hjul Vf 1 500 kr





