



## Volvo V60: K687LG

Vinnumber:	<b>YV1ZWK6VDM2435549</b>	Versionname:	<b>V60 B3 2.0 120kW Business Pro automaat</b>
First Registrationdate:	<b>12/01/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>72349</b>	Power Kw:	<b>120</b>
Bodytype:		Body colour:	<b>Pebble Grey (metallic)</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Parking lot:	<b>566</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

## Options

Number of keys total	<b>3</b>	Telephone equipment
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Front parking sensors
		Rear parking sensors
		Hook

## Degree of wear

225/50/17/98 V				
Winter tyres:	Fr.L.	<b>Dunlop: 5,4 mm</b>	Fr.R.	<b>Dunlop: 4,3 mm</b>
	Re.L.	<b>Dunlop: 5,5 mm</b>	Re.R.	<b>Dunlop: 5,2 mm</b>
Tyre profile depth FL				<b>5.4</b>
Tyre profile depth FR				<b>4.3</b>
Tyre profile depth RL				<b>5.5</b>
Tyre profile depth RR				<b>5.2</b>
Tyre size FL				<b>225/50 R 17 98 V</b>
Tyre size FR				<b>225/50 R 17 98 V</b>
Tyre size RL				<b>225/50 R 17 98 V</b>
Tyre size RR				<b>225/50 R 17 98 V</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>257</b>
Tyre make FR				<b>257</b>
Tyre make RL				<b>257</b>
Tyre make RR				<b>257</b>

## Assistance equipment

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Wing FL, Bad repair, Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper FM, Scratch(es), Replace



Wing RR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Bumper R, Scratch(es), Repair and paint (complete)

