


Vehicle details

VIN	YV1ZWK6VD M2440614	Brand	VOLVO	Maintenance date	-
Licence Plate	K4-68-VG	Model	V60 B3 Automaat Momentum Advantage 5d	Maintenance mileage	-
Registration date	20/03/2021	Year	2021	Exterior Color	Blue Metallic
Odometer	189 825 km	Engine size	1969	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	18/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 225/50/17 Summer 5.0 mm		Michelin 225/50/17 Summer 4.5 mm	
Michelin 225/50/17 Summer 6.0 mm		Michelin 225/50/17 Summer 6.0 mm	

Exterior

4



Part	Alloy wheel 17"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

5



Part	Wing
Position	Back left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

6



Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

7



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

8



Part	Door
Position	Back right
Damages	Improper repair
Severity	-
Repair mode	Repair

9



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

10



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

11



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

12



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

1



●●●

Part	Interior tailgate lining
Position	Back
Damages	Scratched
Severity	-
Repair mode	Smart Repair

2



●

Part	Interior cleaning
Position	Centre
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

3



●●

Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning