



VOLVO V60: FY-980-TR

Vinnnumber:	YV1ZWK6VDM2448746	Versionname:	
First Registrationdate:	23/04/2021	Fiscalpower:	
Expertise Mileage:	187963	Power Kw:	
Bodytype:	Break	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total:	1	Luggage cover
Number keys remote:	1	Rear view camera
GPS big screen color:		

Degree of wear

225/50/17/98 V				
Winter tyres:	Fr.L.	Pirelli: 40%	Fr.R.	Pirelli: 45%
	Re.L.	Pirelli: 70%	Re.R.	Pirelli: 65%
Tyre profile depth FL				5.6
Tyre profile depth FR				5.3
Tyre profile depth RL				3.6
Tyre profile depth RR				3.9
Tyre size FL				225/50 R 17 98 V
Tyre size FR				225/50 R 17 98 V
Tyre size RL				225/50 R 17 98 V
Tyre size RR				225/50 R 17 98 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Remote ignition key (no insert), Missing, Forfeit			



Tyres, No damage, Acceptable



Tyre RL, Out of tolerance, Replace



Alloy rim RL, Scratch(es), Acceptable



Tyre RR, Out of tolerance, Replace



Alloy rim FR, Scratch(es), Acceptable



Door RL, Scratch(es), Paint



Wing RL, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Bumper moulding F, Scratch(es), Paint

Bumper front F, Scratch(es), Paint



Number plate F, Broken, Repair/replace (lump sum)



Bonnet, Scratch(es), Paint



Wing RR, Scratch(es), Polish



Door RR, Scratch(es), Paint



Wing FR, Scratch(es), Paint



Bumper R, Scratch(es), Paint



Reflector, Broken, Replace

