


DEKRA Automotive Solutions

Vehicle details

VIN	YV1ZZK5VC N1088912	Brand	VOLVO	Maintenance date	13/12/2024
Licence Plate	WTD18F	Model	V60-CrossCountry-2018	Maintenance mileage	181 444 km
Registration date	21/10/2021	Year	2021	Exterior Color	Other
Odometer	195 253 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	8		

Inspection Details

Inspection date	15/09/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
LED lighting	✓



Removable element

Refill emergency kit	✓
Load cover	✓

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Key	✓
Remote key	✓

Tyres

Hankook 215/55/18 V Summer 8.0 mm			Hankook 215/55/18 V Summer 8.0 mm		
Hankook 215/55/18 V Summer 8.0 mm			Hankook 215/55/18 V Summer 8.0 mm		

Damages

1



Part	Engine diagnosis
Position	-
Damages	Defective
Severity	-
Repair mode	For info
oil leak	

2



Part	Door
Position	Front left
Damages	Dented
Severity	-
Repair mode	For info

3



Part	Door sill
Position	Front left
Damages	Dented
Severity	-
Repair mode	Smart Repair

4



Part	Door sill
Position	Front left
Damages	Dented
Severity	-
Repair mode	Smart Repair

5



Part	Door
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info

6



Part	Tailgate / Boot door
Position	Back
Damages	Scratched
Severity	-
Repair mode	For info

7



Part	Door
Position	Back right
Damages	Dented
Severity	-
Repair mode	For info

8



Part	Additional winter wheel set
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement