



VOLVO V60 Cross Country

V60 Cross Country B4 D AWD

VIN NO YV1ZZK5VXP2107093
Registration Number VXP2107093



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-11-01	1	2	25306 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-12-12	22491	2022-11-25	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251002142941
Inspection Date / Place	2025-10-02 / BCA Neuss	Cosmetic Grade	1

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1969
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Alloys wheels	Anti-lock braking	Bluetooth telephone interface
Diesel particulate filter	Digitaldashboard	Front fog lamps	Remote adjusting wing mirrors
Reversing Camera	Satellite navigation	Electrically adjustable seats	Electrictailgate
Leather steering wheel	Radio	Airbag Status	AndroidAuto
AppleCarPlay	Cruise control	Digital Radio	Enhanced speaker system
Front parking sensors	Remote central locking	Roof rails	Stability control
Electrically folding wing mirrors	Laneassist	LED Headlamps	Rear parking sensors

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	18
Enhanced Speaker System	Harman/kardon	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

2 Schäden



0 Schäden



Component		Damage	Comments
1	Fender / Back Right	Paint / Scratch / Scuff	
2	Bumper / Back	Paint / Scratch / Scuff	



1. Fender / Back Right
Paint / Scratch / Scuff -



2. Bumper / Back
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	NA	Coolant Fluid	NA
--------------	----	---------------	----

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
❗ <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
☐ <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)