

JEEP Compass Compass 1.5 GSE T4 48V e-Hybrid Automatik



VIN NO ZACNJEBA3PPS43017 Registration Number A3PPS43017

MOT Date

₩-

Number of Owners

2

Last Service

2024-10-10

Last Service Mileage

30450

Number of Keys

P2

First Registration Date

2023-03-29

Odometer Reading

47073 km

Country First Registered

=-

Inspection Report Summary

Customer	BCA Online	Report Number	P20251002152453
Inspection Date / Place	2025-10-02 / BCA Berlin	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Black	Engine Size (cc)	1469
Engine Size	1.5	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Grau	Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			












































Equipment

Right Rear Tyre Depth


5

Tinted Glass	Alloys wheels	Cruise control	Remote adjusting wing mirrors
Reversing Camera	Stability control	LED Headlamps	Airbag Status
Anti-lock braking	Digitaldashboard	Remote central locking	Roof rails
Electrically folding wing mirrors	Radio		
Equipment Details			
Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	18
Air Conditioning Seat Heating	Dual Zone Climate Control Front	Alloy Wheel Size	18
		Alloy Wheel Size	18

Left Rear Tyre Depth

5

Cosmetic Damage



	Component	Damage	Comments
1	Rim / Front Right	Out of Bodywork / Scratch	
2	Rim / Back Right	Out of Bodywork / Scratch	



1. Rim / Front Right Out of Bodywork / Scratch -

2. Rim / Back Right Out of Bodywork / Scratch -

Mechanical Condition

Control Lights			
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	•
Airbag Warning Light	•	Oil Pressure Warning Light	•
Brake Warning Light	•	Power Steering Warning Light	•
Alternator / Battery	•	No Dashboard Lights	•
Display Defect	•	Tire Pressure Monitoring System	⊘
Engine			
Engine Status / EML	•	Engine Leak Visible	•
Engine Starts	•		
Equipments Test			
Electric Windows	•	Audio Equipment	•
AC / Heating System	②	Main & Spare Keys Functioning	②
Parking Sensors / Cameras Functioning	•	Other Equipments	•
Levels			
Brakes Fluid	•	Coolant Fluid	•
Hybrid/EV			
Hybrid System Fault			

Test Drive Inspection

description.

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

User Guide