



JEEP COMPASS II

Compass 1.3 PHEV T4 240 ch 4xe eAWD S

VIN NO ZACPJFEW5NPS08157

Registration Number GQ112PN



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2022-08-26

Odometer Reading



34494 km

Country First Registered



France

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20251017161047
Inspection Date / Place	2025-10-17 / BCA COIGNIERES	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Not Movable	VAT Type	Qualified - Normal Rate
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Gearbox Type	Automatic
Colour	Grey	Engine Size (cc)	1332
Engine Size	1.3	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive
Seat Colour		No of Seats	5
Charging Cables		WLTP CO2 Emissions	
Metalic Colour	GRIS	Electric Consumption	
Accident Damage	Yes	Euro Emission	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			







Equipment


Central locking	Electrically folding wing mirrors	Rear parking sensors	Stability control
Front fog lamps	Power assisted steering	Electrically adjustable seats	Radio
Alloys wheels	Cruise control	Front parking sensors	Satellite navigation

Equipment Details


Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Glass		

Cosmetic Damage

8 Dommages



1 Dommages



Component	Damage	Comments
1 Corner Bumper / Back Right	Paint / Scratch / Scuff	
2 Fender / Front Left	Paint / Scratch / Line	
3 Corner Bumper / Back Right	Paint / Scratch / Line	
4 Door / Back Right	Paint / Chipping	
5 Corner Bumper / Back Left	Paint / Scratch / Line	
6 Door / Back Left	Paint / Chipping	
7 Door / Front Left	Paint / Scratch / Line	
8 Corner Bumper / Back Right	Paint / Chipping	
9 Trunk Carpet	Interior / Dirty	



1. Corner Bumper / Back Right
Paint / Scratch / Scuff -



2. Fender / Front Left
Paint / Scratch / Line -



3. Corner Bumper / Back Right
Paint / Scratch / Line -



4. Door / Back Right
Paint / Chipping -



5. Corner Bumper / Back Left
Paint / Scratch / Line -



6. Door / Back Left
Paint / Chipping -



7. Door / Front Left
Paint / Scratch / Line -



8. Corner Bumper / Back Right
Paint / Chipping -



9. Trunk Carpet
Interior / Dirty -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut ✔

✔ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

❗ *Damages or malfunction detected that requires repairs by the buyer*

NA *Not applicable*

☐ *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.