



MASERATI Ghibli

VIN NO ZAMZS57B001373056
Registration Number GPKW5000



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-07-01	1	2	53420 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-06-11	42495	2021-07-01	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250814115152
Inspection Date / Place	2025-08-14 / BCA Heidenheim	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	3799
Engine Size	3.8	No of Doors	4
Body Type	Sedan	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	USB Socket	Airbag Status	Anti-lock braking
Bluetooth telephone interface	Digital Radio	Remote adjusting wing mirrors	Reversing Camera
Split folding rear seats	Stability control	Electrically adjustable seats	Keyless Entry
LED Headlamps	Rear parking sensors	Trip Computer	360°camera
Alloys wheels	AppleCarPlay	Cruise control	Front parking sensors
Remote central locking	Satellite navigation	Sports seats	Sunroof
Electrically folding wing mirrors	Leather steering wheel	Radio	

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	21
Seat Heating	Front and Rear	Sunroof Type	Tilt/Slide Glass

Wheels & Tyres


Left Front Tyre Depth	7	Right Front Tyre Depth	6
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage


9 Schäden




1 Schäden



Component		Damage	Comments
1	Seat / Front Left	Interior / Worn - out	
2	Fender / Front Left	Paint / Poor Previous Repair	
3	Bumper / Front	Paint / Scratch / Scuff	
4	Hood	Paint / Poor Previous Repair	
5	Back Light / Right	Glass Break	
6	Pillar / Back Right	Bodywork / Dent / Dent	
7	Side Panel / Back Left	Paint / Poor Previous Repair	
8	Door / Front Left	Bodywork / Dent / Dent	
9	Mirror Shell / Front Left	Paint / Scratch / Scuff	
10	Windshield / Front	Glass Break / Impact	



1. Seat / Front Left
Interior / Worn - out -




2. Fender / Front Left
Paint / Poor Previous Repair -



3. Bumper / Front
Paint / Scratch / Scuff -



4. Hood
Paint / Poor Previous Repair -




5. Back Light / Right
Glass Break -



6. Pillar / Back Right
Bodywork / Dent / Dent -




7. Side Panel / Back Left
Paint / Poor Previous Repair -



8. Door / Front Left
Bodywork / Dent / Dent -



9. Mirror Shell / Front Left
Paint / Scratch / Scuff -



10. Windshield / Front
Glass Break / Impact -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)