



ALFA ROMEO MiTo 2013 Benzina
mito 1.4 tb Distinctive Gpl 120cv

VIN NO ZAR9550000X028053
Registration Number EX290XR



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-01-27	-	-	199201 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2015-01-28	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251009115305
Inspection Date / Place	2025-10-09 / BCA Lodi	Cosmetic Grade	5




Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	LPG	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1368
Engine Size	1.4	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	4
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	131

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment


Central locking	Alloys wheels	Volante multifuncion	Remote adjusting wing mirrors
Trip Computer	Stability control	Power assisted steering	Digital Radio
Parcel Shef	Remote central locking	Tyre Mobility Kit	

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Four Seasons	
	KUMHO	195/55//R16 - 91V / 2 mm
	KUMHO	195/55//R16 - 91V / 2 mm
	KUMHO	195/55//R16 - 91V / 3 mm
	KUMHO	195/55//R16 - 91V / 3 mm

23 Danni



6 Danni



46

1

	Component	Damage	Comments
1	Cabin	Interior / Worn - out	
2	Hood	Bodywork / Dent / Hail Area	
3	Seat / Front Left	Interior / Worn - out	
4	Door / Front Left	Paint / Scratch / Line	
5	Roof	Bodywork / Dent / Hail Area	
6	Bumper / Back	Bodywork / Breakage	
7	Pillar / Front Left	Bodywork / Dent / Hail Area	
8	Luggage Space Cover / Back	Interior / Broken	
9	Fender / Back Right	Bodywork / Dent	
10	Floor Carpet	Interior / Broken	
11	Door / Front Right	Paint / Scratch / Line	
12	Mirror Shell / Front Right	Paint / Scratch / Line	

13	Tailgate	Paint / Scratch / Line
14	Bumper / Front	Bodywork / Dent
15	Pillar / Front Right	Bodywork / Dent / Hail Area
16	Fender / Front Right	Bodywork / Dent
17	Fender / Front Left	Bodywork / Dent
18	Bumper / Front	Bodywork / Breakage
19	Rim / Front Left	Out of Bodywork / Scratch
20	Rim / Front Right	Out of Bodywork / Scratch
21	Rim / Back Right	Out of Bodywork / Scratch
22	Fender / Back Left	Bodywork / Dent
23	Rim / Back Left	Out of Bodywork / Scratch
24	Mirror Shell / Front Left	Paint / Scratch / Line
25	Grille / Front	Bodywork / Breakage
26	Windshield / Front	Glass Break
27	Dashboard / Front	Interior / Worn - out
28	Door Handle / Front Right	Bodywork / Breakage
29	Dashboard / Front	Interior / Warning Light ON



1. Cabin
Interior / Worn - out -




2. Hood
Bodywork / Dent / Hail Area -



3. Seat / Front Left
Interior / Worn - out -



4. Door / Front Left
Paint / Scratch / Line -



5. Roof
Bodywork / Dent / Hail Area -




6. Bumper / Back
Bodywork / Breakage -



7. Pillar / Front Left
Bodywork / Dent / Hail Area -




8. Luggage Space Cover / Back
Interior / Broken -



9. Fender / Back Right
Bodywork / Dent -



10. Floor Carpet
Interior / Broken -



11. Door / Front Right
Paint / Scratch / Line -



12. Mirror Shell / Front Right
Paint / Scratch / Line -



13. Tailgate
Paint / Scratch / Line -



14. Bumper / Front
Bodywork / Dent -



15. Pillar / Front Right
Bodywork / Dent / Hail Area -



16. Fender / Front Right
Bodywork / Dent -



17. Fender / Front Left
Bodywork / Dent -



18. Bumper / Front
Bodywork / Breakage -



19. Rim / Front Left
Out of Bodywork / Scratch -



20. Rim / Front Right
Out of Bodywork / Scratch -



21. Rim / Back Right
Out of Bodywork / Scratch -



22. Fender / Back Left
Bodywork / Dent -



23. Rim / Back Left
Out of Bodywork / Scratch -



24. Mirror Shell / Front Left
Paint / Scratch / Line -



25. Grille / Front
Bodywork / Breakage -



26. Windshield / Front
Glass Break -



27. Dashboard / Front
Interior / Worn - out -



28. Door Handle / Front Right
Bodywork / Breakage -



29. Dashboard / Front
Interior / Warning Light ON -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	!

Test Drive Inspection

General			
Test Driven Status	✓	Test Drive Comment	SPIA MOTORE ACCESA.
Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested