



ALFA ROMEO Giulia

Giulia 2.2 Diesel

VIN NO ZAREAECUXH7519838
Registration Number UXH7519838



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-09-01	-	1	204390 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2017-01-30	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250523112216
Inspection Date / Place	2025-05-23 / BCA Neuss	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Red	Engine Size (cc)	2143
Engine Size	2.1	No of Doors	4
Body Type	Sedan	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	109

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	
Manufacturer Warrenty			







Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Cruise control
Front fog lamps	Remote adjusting wing mirrors	Satellite navigation	Radio
USB Socket	Alloys wheels	Bluetooth telephone interface	Diesel particulate filter
Front parking sensors	Remote central locking	Leather steering wheel	Rear parking sensors

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
------------------	---------------------------	------------------	----

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

22 Damages




0 Damages



Component		Damage	Comments
1	B Pillar / Center Left	Bodywork / Dent / Dent	
2	Rocker Panel / Center Right	Bodywork / Dent / Dent	
3	Windshield / Front	Glass Break / Impact	
4	Windshield / Front	Glass Break / Impact	
5	Hood	Bodywork / Dent / Dent	
6	Hood	Bodywork / Dent / Dent	
7	Hood	Paint / Stone Chip	
8	Corner Bumper / Front Right	Paint / Scratch / Scuff	
9	Corner Bumper / Front Left	Paint / Scratch / Scuff	
10	Rim / Front Left	Out of Bodywork / Scratch	
11	Side Panel / Back Left	Bodywork / Dent / Dent	
12	Side Panel / Back Left	Bodywork / Dent / Dent	
13	Roof	Bodywork / Dent / Dent	


14	Roof	Paint / Corrosion
15	Roof	Bodywork / Dent / Dent
16	Roof	Bodywork / Dent / Dent
17	Roof	Bodywork / Dent / Dent
18	Tailgate	Bodywork / Dent / Dent
19	Side Panel / Back Right	Bodywork / Dent / Dent
20	Side Panel / Back Right	Bodywork / Dent / Dent
21	Door Joint / Front Left Middle	Bodywork / Breakage
22	B Pillar / Center Left	Bodywork / Breakage



1. B Pillar / Center Left
Bodywork / Dent / Dent -




2. Rocker Panel / Center Right
Bodywork / Dent / Dent -




3. Windshield / Front
Glass Break / Impact -



4. Windshield / Front
Glass Break / Impact -



5. Hood
Bodywork / Dent / Dent -



6. Hood
Bodywork / Dent / Dent -



7. Hood
Paint / Stone Chip -




8. Corner Bumper / Front Right
Paint / Scratch / Scuff -



9. Corner Bumper / Front Left
Paint / Scratch / Scuff -




10. Rim / Front Left
Out of Bodywork / Scratch -




11. Side Panel / Back Left
Bodywork / Dent / Dent -




12. Side Panel / Back Left
Bodywork / Dent / Dent -




13. Roof
Bodywork / Dent / Dent -




14. Roof
Paint / Corrosion -




15. Roof
Bodywork / Dent / Dent -



16. Roof
Bodywork / Dent / Dent -



17. Roof
Bodywork / Dent / Dent -




18. Tailgate
Bodywork / Dent / Dent -



19. Side Panel / Back Right
Bodywork / Dent / Dent -



20. Side Panel / Back Right
Bodywork / Dent / Dent -



21. Door Joint / Front Left Middle
Bodywork / Breakage -



22. B Pillar / Center Left
Bodywork / Breakage -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	!	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	NA	Coolant Fluid	✓
--------------	----	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)