

INSPECTION REPORT



End Of Contract

GENERAL INFO

File	280564
License plate	VL4269
Vehicle identification number	ZARPAGBX3K7C36644
Dossier	2019 053 063
Make	Alfa Romeo Stelvio 2.2JTD160 B
Mileage	173355.00
First registration	16/04/2019
	08/05/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	



DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
41	Windshield // Replace	N
54	Headlight / Front left / Replace	Y
72	Side View Mirror Left // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
139	Bumper Rear / Spoiler / Replace	N
163	Roof // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	N
222	Side View Mirror Right // Painting	N
244	Light / Front Right / Replace	Y
411	Seat Front Left // Repair	Y
421	Seat Front Right // Repair	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Light / Front Right / Replace-scratch



Side View Mirror Right // Painting-scratch



Seat Front Right // Repair-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Front Left // Repair-scratch



Side View Mirror Left // Painting-scratch



Headlight / Front left / Replace-scratch



Roof // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Bumper Rear / Lower Cover Not Painted / Replace-cracked



Bumper Rear / Spoiler / Replace-cracked



Bumper Front // Replace & Painting-cracked



Windshield // Replace-glass damage