



IVECO DAILY
DAILY CDC 35 C 14H EMP 3750 QUAD-
LEAF BVM6

VIN NO ZCFCL35A205618715
Registration Number GW709NY



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	12423 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2024-04-24	France

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250523103812
Inspection Date / Place	2025-05-23 / BCA AUNAY	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	2287
Engine Size	2.3	No of Doors	4
Body Type	Double cabin platform truck	Drive Train	Rear
Seat Colour		No of Seats	7
Seat Covering Name		Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			





Equipment

Central locking	Rear parking sensors	Cruise control	Power assisted steering
Radio	Stability control	Front fog lamps	



Equipment Details

Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

Wheels & Tyres

Left Rear Tyre Depth	2	Left Front Tyre Depth	2
Right Rear Tyre Depth	2	Right Front Tyre Depth	2

Cosmetic Damage

1 Dommages		0 Dommages	
			
Component	Damage	Comments	
1 Roof	Bodywork / Dent / Deformation		



1. Roof
Bodywork / Dent / Deformation -

Mechanical Condition

Levels

Coolant Fluid - Condition	✓	Oil - Condition	NA
Level - Oil	✓	Coolant Fluid	✓
Brakes Fluid	✓		

Tyres

Presence Anti-Theft Lock Nut	✓
------------------------------	---

Dashboard Lights

ABS Warning Light	✓	Transmission Warning Light	✓
Diesel Particulate Filter Light	✓	ESP Fault/Traction Control Malfunction Light	✓
4WD Light	NA	Service Light	✓
Dashboard Working	✓	Engine Light	!
Oil Pressure Warning Light	✓	Airbag Warning Light	✓
Brake Warning Light	✓	Steering Fluid Level	✓
Level - Fuel / Battery	15		

Equipments Test

Main & Spare Keys Functioning	!	Electric Windows	✓
Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA	AC / Heating System	NA
Parking Sensors / Cameras Functioning	NA	Central Locking	✓
Audio Equipment	✓	Navigation System	NA

Engine

Cross Member	NA
--------------	----

Test Drive Inspection

Test Drive

Engine functioning	NA	Vehicle Starts	✓
--------------------	----	----------------	---

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA *Not applicable*

— *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.